

Ultimate

Drive thru Windows

18518 24th Ave, Surrey, BC, V3S 9V2

(604)-541-1801 Fax (604)-541-2557 tf: 1-(888)-300-9493

Website: www.drivethru.ca

Replacement of Series 3 Maximizer Inlet Filter – Part #S3-IFE

- Locate current inlet filter cover
- To remove, push up and turn one third counterclockwise
- Remove old inlet filter and discard
- Put on new inlet filter
- Put inlet filter cover back on by lining up the bayonet fittings then pushing up and turn clockwise one third

Link to how to video:

<https://youtube.com/shorts/fGNQErny8D0?feature=share>

QR Code to how to video:

